



Client Name: FTBS
Project Name: Essex

Site ID: c21b7a21
Site Address: 68 Victoria Rd, Romford RM1 2LA, UK

Operative Name: Brad
Job Type: Breakdown
Is the Job Complete?: YES
Comments:

Date: 28/11/2021
Time On Site: 16:59
Time Off Site: 18:02
Duration: 01:03

Property Photos

Photo	Comments	Date time
-------	----------	-----------

Parts/Materials Used

Group	Description of Item	Qty	Unit Cost	Total Cost
Pumps	Replacement pump	3	£90.50	£271.50

Photos

Photo	Comments	Date/Time
-------	----------	-----------

Total:	£271.50
---------------	----------------

Client Name: FTBS
 Project Name: Essex

Site ID: c21b7a21
 Site Address: 68 Victoria Rd, Romford RM1 2LA, UK

Operative Name: Brad
 Job Type: Breakdown
 Is the Job Complete?: YES
 Comments:

Date: 29/11/2021
 Time On Site: 11:58
 Time Off Site: 18:02
 Duration: 06:04



Property Photos


Photo	Comments	Date time
		29/11/2021 08:41:58

Parts/Materials Used

Group	Description of Item	Qty	Unit Cost	Total Cost
Boilers	Replace back boiler for combi	1	£1,500.00	£1,500.00

Photos

Photo	Comments	Date/Time
		29/11/2021 12:49:55
		29/11/2021 12:56:05

		29/11/2021 13:18:11
----------------------------------------------------------------------------------	--	------------------------

	Total: £1,500.00
--	-------------------------


Client Name: FTBS
 Project Name: Essex

Site ID: 55c27e6d
 Site Address: 158 High Rd, Baker Street, Orsett, Grays RM16 3LH, UK

Operative Name: Bradley Davis
 Job Type: Breakdown
 Is the Job Complete?: YES
 Comments:

Date: 29/11/2021
 Time On Site: 13:17
 Time Off Site: 18:02
 Duration: 04:45


Property Photos

Photo	Comments	Date time
		29/11/2021 09:29:21

Parts/Materials Used

Group	Description of Item	Qty	Unit Cost	Total Cost
Pumps	Install new pump	2	£120.00	£240.00


Photos

Photo	Comments	Date/Time
		29/11/2021 09:08:56

Parts/Materials Used

Group	Description of Item	Qty	Unit Cost	Total Cost
Boilers	Replace back boiler for combi	1	£1,500.00	£1,500.00

Photos

Photo	Comments	Date/Time
		29/11/2021 13:17:49

Parts/Materials Used

Group	Description of Item	Qty	Unit Cost	Total Cost
Pumps	Replacement pump	3	£90.50	£271.50

Photos

Photo	Comments	Date/Time
-------	----------	-----------

Total:	£2,011.50
---------------	------------------




Client Name: FTBS
Project Name: Essex

Site ID: 55c27e6d
Site Address: 158 High Rd, Baker Street, Orsett, Grays RM16 3LH, UK

Operative Name: Brad
Job Type: Breakdown
Is the Job Complete?: YES
Comments:

Date: 29/11/2021
Time On Site: 10:22
Time Off Site: 10:24
Duration: 00:02

Property Photos

Photo	Comments	Date time
		29/11/2021 09:27:18

Total:	£0.00
---------------	--------------



Client Name: FTBS
Project Name: Essex

Site ID: b534c6b0
Site Address: 55 Southend Rd, Stanford-le-Hope SS17 0PE, UK

Operative Name: Bradley Davis
Job Type: Service Call
Is the Job Complete?: YES
Comments:

Date: 29/11/2021
Time On Site: 09:42
Time Off Site: 09:42
Duration: 00:00

Property Photos

Photo	Comments	Date time
-------	----------	-----------

Total:	£0.00
---------------	--------------



Client Name: FTBS
Project Name: Essex

Site ID: 55c27e6d
Site Address: 158 High Rd, Baker Street, Orsett, Grays RM16 3LH, UK

Operative Name: Brad
Job Type: Breakdown
Is the Job Complete?: YES
Comments:

Date: 29/11/2021
Time On Site: 13:26
Time Off Site: 15:55
Duration: 02:29


Property Photos

Photo	Comments	Date time
-------	----------	-----------

Parts/Materials Used

Group	Description of Item	Qty	Unit Cost	Total Cost
Pumps	Replacement pump	1	£90.50	£90.50

Photos

Photo	Comments	Date/Time
	It was broken	29/11/2021 13:25:28

Total:	£90.50
---------------	---------------

Client Name: FTBS
 Project Name: Essex

Site ID: c21b7a21
 Site Address: 68 Victoria Rd, Romford RM1 2LA, UK

Operative Name: Brad
 Job Type: Breakdown
 Is the Job Complete?: YES
 Comments:

Date: 30/11/2021
 Time On Site: 10:51
 Time Off Site: 10:55
 Duration: 00:04

Property Photos

Photo	Comments	Date time
-------	----------	-----------

Parts/Materials Used

Group	Description of Item	Qty	Unit Cost	Total Cost
Pumps	Replacement pump	1	£90.50	£90.50

Photos

Photo	Comments	Date/Time
		30/11/2021 10:52:02

Total:	£90.50
---------------	---------------



Client Name: FTBS
Project Name: Essex

Site ID: b534c6b0
Site Address: 55 Southend Rd, Stanford-le-Hope SS17 0PE, UK

Operative Name: Brad
Job Type: Breakdown
Is the Job Complete?: YES
Comments:

Date: 30/11/2021
Time On Site: 11:18
Time Off Site: 11:18
Duration: 00:00

Property Photos

Photo	Comments	Date time
-------	----------	-----------

Parts/Materials Used

Group	Description of Item	Qty	Unit Cost	Total Cost
Boilers	New baxi combi install	1	£1,000.00	£1,000.00

Photos

Photo	Comments	Date/Time
		30/11/2021 11:03:49

Total:	£1,000.00
---------------	------------------

Client Name: FTBS
Project Name: Essex

Site ID: b534c6b0
Site Address: 55 Southend Rd, Stanford-le-Hope SS17 0PE, UK

Operative Name: Brad
Job Type: Breakdown
Is the Job Complete?: NO
Comments: Job all going well

Date: 30/11/2021
Time On Site: 12:21
Time Off Site: 12:21
Duration: 00:00

Property Photos

Photo	Comments	Date time
		30/11/2021 12:21:32

Total:	£0.00
---------------	--------------



Client Name: FTBS
Project Name: Essex

Site ID: 55c27e6d
Site Address: 158 High Rd, Baker Street, Orsett, Grays RM16 3LH, UK

Operative Name: Bradley Davis
Job Type: Breakdown
Is the Job Complete?: YES
Comments:

Date: 30/11/2021
Time On Site: 14:26
Time Off Site: 14:26
Duration: 00:00

Property Photos

Photo	Comments	Date time
-------	----------	-----------

Parts/Materials Used

Group	Description of Item	Qty	Unit Cost	Total Cost
Pumps	Replacement pump	1	£90.50	£90.50

Photos

Photo	Comments	Date/Time
-------	----------	-----------

Total:	£90.50
---------------	---------------



Client Name: FTBS
Project Name: Essex

Site ID: 55c27e6d
Site Address: 158 High Rd, Baker Street, Orsett, Grays RM16 3LH, UK

Operative Name: Bradley Davis
Job Type: Breakdown
Is the Job Complete?: YES
Comments:

Date: 30/11/2021
Time On Site: 14:33
Time Off Site: 14:38
Duration: 00:05

Property Photos

Photo	Comments	Date time
-------	----------	-----------

Total:	£0.00
---------------	--------------



Client Name: FTBS
Project Name: Essex

Site ID: c21b7a21
Site Address: 68 Victoria Rd, Romford RM1 2LA, UK

Operative Name: Bradley Davis
Job Type: Breakdown
Is the Job Complete?: YES
Comments:

Date: 30/11/2021
Time On Site: 14:12
Time Off Site: 14:44
Duration: 00:32

Property Photos

Photo	Comments	Date time
-------	----------	-----------

Total:	£0.00
---------------	--------------



Client Name: FTBS
Project Name: Essex

Site ID: b534c6b0
Site Address: 55 Southend Rd, Stanford-le-Hope SS17 0PE, UK

Operative Name: Bradley Davis
Job Type: Service Call
Is the Job Complete?: YES
Comments:

Date: 30/11/2021
Time On Site: 14:45
Time Off Site: 14:47
Duration: 00:02

Property Photos

Photo	Comments	Date time
-------	----------	-----------

Total:	£0.00
---------------	--------------
